Bioretention Area Inspection and Maintenance Checklist

| E. 224 E. 2.1.21 B | |
|---|--------------------------------------|
| Facility: Fairhill Partners Location/Address: 12200 Fairhill Rd, Cleveland, OH 44120 | |
| Location/Address: 12200 Fairnin Ru, Cieveiand, Ori 44120 | |
| Date:7/2/2019 Time: 11:17am Weather Conditions | : Sunny Date of Last Inspection: N/A |
| Inspector: Chris Hartman, CPESC, CESSWI, CPSWQ, | Title: Inspection Report |
| Stormwater Technical Specialist, Crystal Davis, Watershe | d |
| Programs Specialist, Spencer Nash, Watershed Programs Intern, Jessica Cotton, GIS Technician | |
| Rain in Last 48 Hours | |
| Pavement Type: □ permeable interlocking concrete pavement (PICP) □ asphalt □ concrete □ other, specify: | |
| Pretreatment: vegetated filter strip swale turf grass forebay other, specify: | |
| Site Plan or As-Built Plan Available: □ Yes ✓ No | |
| Action items are noted below in SUMMARY section. | |
| | T- |
| Inspection Item | Images |
| 1. PRETREATMENT | |
| Sediment has accumulated. ☐ Yes ✓ No ☐ NA | |
| LICS VINO LINA | |
| | |
| | |
| Trash and debris have accumulated. | |
| □ Yes ✓ No □ NA | |
| _ | |
| | |
| Action needed. | |
| □ Yes ✓ No □ NA | |
| | |
| Comments: No additional comments | |
| Comments: No additional comments | 第一人的人 的意思, |
| | |
| 2. DEWATERING | Photo 1 (Refer to action item 1). |
| | |
| Standing water is present after 24 hours. If yes, describe | |
| sheen, color, or smell. □ Yes No □ NA | they |
| LIYES INO LINA | |
| | |
| Action needed. | |
| □ Yes ✓ No □ NA | |
| Comments: No additional comments. | |
| | |
| 3. INLETS | |
| Inlets are in poor structural condition. | |
| □ Yes ✓ No □ NA | |
| Sediment has accumulated and/or is blocking the inlets. | |
| □Yes ✓No □NA | |
| Erosion is occurring around the inlets. | |
| □ Yes ✓ No □ NA | |
| Action needed. | Photo 2 (Pafor to nation item 1) |
| □ Yes ✓ No □ NA | Photo 2 (Refer to action item 1). |
| | |
| Comments No. 1122 | - |
| Comments: No additional comments. | |
| | |

| 4. VEGETATION |
|---|
| Vegetation is wilting, discolored, or dying due to disease or |
| stress. |
| Yes □ No □ NA |
| Vegetation needs to be controlled through mowing or |
| manual removal. |
| ☐ Yes ☑ No ☐ NA |
| Action needed. |
| ☐ Yes ✓ No ☐ NA |
| Comments: Several trees are dying and or are dead. |
| Comments. Several trees are dying and of are dead. |
| 5. BIORETENTION MAIN INFILTRATION AREA |
| Trash and debris have accumulated. |
| ☐ Yes ✓ No ☐ NA |
| Sediment has accumulated at the surface. |
| ☐ Yes ✓ No ☐ NA |
| Topmost layer is caked or crusted over with sediment. |
| ✓ Yes □No □ NA |
| Erosion is evident. |
| ☐ Yes ✓ No ☐ NA |
| Mulch is compacted. |
| ☐ Yes ✓ No ☐ NA |
| Sinkholes or animal borrows are present. |
| ☐ Yes ✓ No ☐ NA Action needed. |
| |
| ☐ Yes ✓ No ☐ NA |
| Comments: Small layer of sediment is present on top of the |
| bioretention cell. |
| |
| 6. SIDE SLOPES AND EMBANKMENT |
| Erosion is evident. |
| ☐ Yes ✓ No ☐ NA |
| Sinkhol <u>es</u> or animal borrows are present. |
| □ Yes ✓ No □ NA |
| Action needed. |
| ☐ Yes ✓ No ☐ NA |
| Comments: No additional comments. |
| Comments To additional Comments. |
| 7. OUTLETS AND OVERFLOW STRUCTURE (i.e., |
| catch basin) |
| Outlets or overflow structures in poor structural condition. |
| ☐ Yes No ☐ NA |
| Sediment, trash or debris is blocking the outlets or |
| overflow structure. |
| ☐ Yes ✓ No ☐ NA |
| Erosion is occurring around the outlets or overflow |
| structure |
| ☐ Yes ✓ No ☐ NA |
| Height from surface of practice to top of overflow structure |
| is insufficient to allow for ponding during rain events. |
| |
| ☐ Yes ✓ No ☐ NA |
| ☐ Yes ✓ No ☐ NA Action needed. |
| Action needed. |
| Action needed. ☐ Yes ☑ No ☐ NA |
| Action needed. □ Yes ✓ No □ NA Action needed. |
| Action needed. ☐ Yes ☑ No ☐ NA |
| Action needed. □ Yes ✓ No □ NA Action needed. |
| Action needed. ☐ Yes ✓ No ☐ NA Action needed. |
| Action needed. ☐ Yes ✓ No ☐ NA Action needed. |

SUMMARY

Additional Action Required:

To be in compliance, the applicant needs to address the following:

1. Inform applicant that several trees have died and will need to be replaced. Furthermore, a small layer of sediment has been found on top of the middle area of the bioretention cell. The sediment should be removed and disposed of properly (Refer to photos 1 & 2).