



Bioretention Area Inspection and Maintenance Checklist

Green Infrastructure Site Location and Address: MLK Carnegie Infrastructure Project, Intersection of MLK Jr. Dr & Carnegie Ave		
Date and Time: 07/16/2019 10:35am	Weather Conditions: ☀️ Sunny	Date of Last Inspection: N/A
Inspector and Title: Chris Hartman, CPESC, CESSWI, CPSWQ, Stormwater Technical Specialist, Crystal Davis, Watershed Programs Specialist, Spencer Nash, Watershed Programs Intern		
Site Plan or As-Built Plan Available: Yes		

Inspection Item	Images
DEWATERING	
<p>Standing water is present after 24 hours. If yes, describe sheen, color, or smell. <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> NA</p>	
<p>Action needed. <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> NA</p>	
<p>Comments: No additional comments</p>	
INLETS	
<p>Inlets are in poor structural condition. <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> NA</p>	<p>Photo 1.</p> <p>-----</p> <p>-----</p> 
<p>Sediment has accumulated and/or is blocking the inlets. <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> NA</p>	
<p>Erosion is occurring around the inlets. <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> NA</p>	
<p>Action needed. <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> NA</p>	
<p>Comments: Erosion is occurring around the eastern inlet. Applicant will need to stabilize erosion through means of rock inlet protection or re-mulching the area (Refer to photo 3).</p>	
VEGETATION	
<p>Vegetation is wilting, discolored, or dying due to disease or stress. <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> NA</p>	<p>Photo 2.</p> <p>-----</p> <p>-----</p>
<p>Vegetation needs to be controlled through mowing or manual removal. <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> NA</p>	
<p>Action needed. <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> NA</p>	

Comments: Applicant will need to weed the cell.

BIORETENTION MAIN INFILTRATION AREA

Trash and debris have accumulated.

☐ Yes ☒ No ☐ NA

Sediment has accumulated at the surface.

☐ Yes ☒ No ☐ NA

Topmost layer is caked or crusted over with sediment.

☐ Yes ☒ No ☐ NA

Erosion is evident.

☐ Yes ☒ No ☐ NA

Mulch is compacted.

☐ Yes ☒ No ☐ NA

Sinkholes or animal borrows are present.

☐ Yes ☒ No ☐ NA

Action needed.

☐ Yes ☒ No ☐ NA

Comments: No additional comments



Photo 3.

SIDE SLOPES AND EMBANKMENT

Erosion is evident.

☐ Yes ☒ No ☐ NA

Sinkholes or animal borrows are present.

☐ Yes ☒ No ☐ NA

Action needed.

☐ Yes ☒ No ☐ NA

Comments: No additional comments.

OUTLETS AND OVERFLOW STRUCTURE (i.e., catch basin)

Outlets or overflow structures in poor structural condition.

☐ Yes ☒ No ☐ NA

Sediment, trash or debris is blocking the outlets or overflow structure.

☐ Yes ☒ No ☐ NA

Erosion is occurring around the outlets or overflow structure.

☐ Yes ☒ No ☐ NA

Height from surface of practice to top of overflow structure is insufficient to allow for ponding during rain events.

☐ Yes ☒ No ☐ NA

Action needed.

☐ Yes ☒ No ☐ NA

Action needed.

Note: No additional comments.

SUMMARY

Please address the following items:

1. Ensure the erosion occurring at the eastern inlet is stabilized (runoff inflow appears to be running along the side of the rock inlet protection...reform the rock into a concave shape).
2. Weed the practice to reduce the amount of invasive species. **Refer to photo 3. for the location that has erosion.**