# Bioretention Area Inspection and Maintenance Checklist (EAST BASIN)

Facility: ST. CASIMIR  Location/Address: 8223 SOW/WSK/ Cleve IAWP  Date: S/26/2/ Time: /OAW Weather Conditions: Clevely Date of Last Inspection: NOTSUFC  Inspector: Tolaw Weather Conditions: Clevely Date of Last Inspection: NOTSUFC  Rain in Last 48 Hours Yes No If yes, list amount and timing: See Photos  Pretreatment: vegetated filter strip swale turf grass forebay other, specify: none  Site Plan or As-Built Plan Available: Yes No			
Inspection Item		Comment	Action Needed
1. PRETREATMENT	2 2.2		1,000
Sediment has accumulated.	□Yes ☑No □N/A		□Yes □No
Trash and debris have accumulated.	□Yes □No □N/A	·	□Yes □No
2. DEWATERING Standing water is present after 24 hours.			
If yes, describe sheen, color, or smell.  3. INLETS	Yes No N/A		□Yes □No
Inlets are in poor structural condition.	□Yes ☑No □N/A		☐Yes ☑No
Sediment has accumulated and/or is blocking the inlets.	□Yes ☑No □N/A		□Yes □No
Erosion is occurring around the inlets.	□Yes ☑No □N/A		□Yes □No
3. VEGETATION	, J.,		
Vegetation is wilting, discolored, or dying due to disease or stress.	□Yes ☑No □N/A		□Yes □No
Vegetation needs to be controlled through	Day Chr. Day		
mowing or manual removal.  4. BIORETENTION MAIN INFILTRA	Yes No NA		Yes No
7	I ION AREA		T
Trash and debris have accumulated.	□Yes □No □N/A		□Yes ☑No
Sediment has accumulated at the surface.	□Yes ☑No □N/A		☐Yes ☐No
Topmost layer is caked or crusted over with sediment.	□Yes ☑No □N/A		□Yes ☑No
Erosion is evident.	□Yes □No □N/A		□Yes □No
Mulch is compacted.	□Yes □No □N/A		□Yes □No
Sinkholes or animal borrows are present.	□Yes □No □N/A		☐Yes ☐No
5. SIDE SLOPES AND EMBANKMEN	Γ		т
Erosion is evident.	☐Yes ☐No ☐N/A		□Yes □No
Sinkholes or instability is evident.	□Yes □No □N/A		☐Yes ☐No
6. OUTLETS AND OVERFLOW STRUCTURE (i.e., catch basin)			
Outlets or overflow structures in poor structural condition.	□Yes □No □N/A		□Yes □No
Sediment, trash or debris is blocking the outlets or overflow structure.	□Yes ☑No □N/A		□Yes □No
Erosion is occurring around the outlets or overflow structure.	□Yes ☑No □N/A		□Yes ☑No
Height from surface of practice to top of overflow structure is insufficient to allow	□Yes □No □N/A		□Yes ☑No

for ponding during rain events.

#### **Additional Notes**

See Photos.

BASIN IN 600D SHAPE 
NEW MULCH WAS ADDER JONE 2020.

PLANTINGS OF SHRUBS / KLOWERS

STILL BEING DISCUSSED.

Wet weather inspection needed ☐ Yes ☐ No

Site Sketch:

## East Basin (Behind Rectory and Church) Photo taken 5-26-21

Basin with new mulch added June/ 2020



East Basin (Behind Rectory and Church) Photo taken 5-26-21 Inlet pipe from rectory gutters



Outlet pipe at East basin behind rectory and church (photo taken 5-26-21



# ( DURING RAIN EVENT)

East Basin-Photo taken 5/9/21 during 1.8" rainfall event showing complete infiltration



# East basin signage in good shape



# Bioretention Area Inspection and Maintenance Checklist (WEST BASIN)

Facility: ST (ASIMIR	
Location/Address: 8223 Sowinsk Clebe LAND	<u> </u>
Date: 5/26/21 Time: 10Am Weather Conditions: CLOUPY Date of Last Inspection:	
Inspector: John NIED ZIALEK Title: CPFSC	~
Rain in Last 48 Hours ZYes No If yes, list amount and timing:	
Pretreatment: vegetated filter strip swale turf grass forebay other, specify:	none 🗆
Site Plan or As-Built Plan Available: Yes 🗆 No	

Inspection Item		Comment	Action Needed
1. PRETREATMENT			
Sediment has accumulated.	□Yes □No □N/A		□Yes ☑No
Trash and debris have accumulated.	□Yes ☑No □N/A		□Yes □No
2. DEWATERING			
Standing water is present after 24 hours. If yes, describe sheen, color, or smell.  3. INLETS	□Yes □N0 □N/A		□Yes □No
		<u></u>	
Inlets are in poor structural condition.	□Yes ☑No □N/A		□Yes ☑No
Sediment has accumulated and/or is blocking the inlets.	□Yes ☑No □N/A		□Yes ☑No
Erosion is occurring around the inlets.	✓Yes □No □N/A	MINOR-REPLACE	□Yes □No
3. VEGETATION			
Vegetation is wilting, discolored, or dying due to disease or stress.	□Yes □No □N/A		□Yes □No
Vegetation needs to be controlled through mowing or manual removal.	□Yes ☑No □N/A		□Yes □No
4. BIORETENTION MAIN INFILTRAT	TION AREA		
Trash and debris have accumulated.	□Yes □Xo □N/A		□Yes □No
Sediment has accumulated at the surface.	□Yes □No □N/A		□Yes ☑No
Topmost layer is caked or crusted over with sediment.	□Yes ☑No □N/A		□Yes □No
Erosion is evident.	□Yes ☑No □N/A		□Yes □No
Mulch is compacted.	□Yes ZNo □N/A	, ,	□Yes ☑No
Sinkholes or animal borrows are present.	✓Yes □No □N/A	SINKHOLE WAS REPAIRED BY ADDING ROCK IN 2019	□Yes ☑No
5. SIDE SLOPES AND EMBANKMENT	<u> </u>	ADDING ROCK IN 2019	7
Erosion is evident.	□Yes □No □N/A		□Yes □No
Sinkholes or instability is evident.	□Yes □No □N/A		□Yes ☑No
6. OUTLETS AND OVERFLOW STRUCTURE (i.e., catch basin)			
Outlets or overflow structures in poor structural condition.	□Yes ☑No □N/A		□Yes □No
Sediment, trash or debris is blocking the outlets or overflow structure.	□Yes ☑No □N/A		□Yes □No
Erosion is occurring around the outlets or overflow structure.	□Yes ☑No □N/A		□Yes □No
Height from surface of practice to top of overflow structure is insufficient to allow for ponding during rain events.	□Yes .☑No □N/A		□Yes □No

**Additional Notes** 

See Photos

Photos show into existing

CONDITION AS OF 5/26/21

Photo shows

INFILTRATION RATE ON

MAY 9,2021 DURING

RAIN FUENT.

Site Sketch:

West Basin (behind old convent building) Photo taken 5/26/2021

New mulch was added June 2020 (some minor scouring near inlet pipe



West Basin (behind old convent building) Photo taken 5/26/2021

Noting area of repair made in 2019 where rock was placed in area that was sinking )-still appears stable). This area may require future maintenance to monitor any new sinking.



Showing west basin signage still in place-photo taken 5-26-2021



Showing West Basin on May 9, 2021 during 1.8" rainfall event.

Positive Infiltration /Outlet ok




INLET WITH SURROUNDING PAVER BY GARAGE

## Permeable Pavement Inspection and Maintenance Checklist

Facility: 57. C/15/M/F  Location/Address: 8223 SOW/OST CLEVELAND  Date: 5/26/9 Time: 6.0 Weather Conditions: Date of Last Inspection:  Inspector: Title: C/15/M/F  Rain in Last 48 Hours December 1900 If yes, list amount and timing: See P/10 to SEE P/10 P/10 SEE P/10 SEE P/10 P/10 SEE P/10 SEE P/10 SEE P/10 P/10 SEE P			
Inspection Item		Comment	Action Needed
1. PRETREATMENT	· -		
Sediment has accumulated.	□Yes ☑No □N/A		□Yes □No
Trash and debris have accumulated.	□Ves □No □N/A	BRICKS HELPFUL	☐Yes □No
2. PAVEMENT TRANSITION AREA		BAICH > PICLAPOL	T
Non-permeable transition area at pavement edges is unstable/deteriorating.	□Yes □N₀ □N/A		Yes No
3. DEWATERING	<u>-</u>	<del></del>	
Standing water is visible on the surface after a rain event.	Yes No N/A		□Yes □No
4. PAVEMENT SURFACE AND JOINT	i'S		· · · · · · · · · · · · · · · · · · ·
Sediment has accumulated on pavement surface.	□Yes □No □N/A		□Yes ☑No
Trash and debris have accumulated on pavement surface or around curbing.	□Yes □No □N/A	See ABove	∠Yes □No
Pavement has deteriorated, cracked, settled, or raveled.	□Yes □No □N/A		☐Yes ☐No
Sediment has accumulated in the joints of PICP.	□Yes ☑No □N/A		☐Yes ☐No
Vegetation is growing in the joints of PICP.	□Yes ☑No □N/A		□Yes □No
Gravel is insufficient in the joints of PICP.	□Yes ☑No □N/A		□Yes □No
Additional Notes			
AREA WA	5 CLPAN	IED NOVEMBER	
Wet weather inspection needed Ves	n No		

Inlet with surrounding pavers-photo taken 5-26-21. Additional cleaning would help between pavers. Pavers were cleaned November 2020.



Close up photo on May 26, 2021



Inlet with surrounding pavers-photo taken May 9, 2021 during 1.8" rain event . Infiltration is occurring.



# EAST LOT - Between church & HALL Permeable Pavement Inspection and Maintenance Checklist

Facility: ST (ASIMIR			
Location/Address: 9223	SowInst/	CLEVELARP	
Date: 5/24/3/ Time: Weather Conditions: Date of Last Inspection:			
Inspector: John NIED		le: CPFSCS	
Rain in Last 48 Hours Ves No	If yes, list amount and	timing: Seephotos F	Rom 5/9/
Pavement Type: permeable interlocking	ng concrete pavement (PI	CP) asphalt concrete other, spe	cify:
Pretreatment:   vegetated filter strip	swale □ turf grass □ fo	rebay other, specify:	□ none
Site Plan or As-Built Plan Available: D			
*Permeable interlocking concrete pavemen	(PICP)		
Inspection Item		Comment	Action Needed
1. PRETREATMENT			
Sediment has accumulated.	□Yes □No □N/A		□Yes □No
Trash and debris have accumulated.	□Yes □No □N/A		□Yes □No
2. PAVEMENT TRANSITION AREA			
Non-permeable transition area at			
pavement edges is unstable/deteriorating.	□Yes □No □N/A		Yes No
3. DEWATERING			
Standing water is visible on the surface			
after a rain event.	□Yes □No □N/A		Yes No
4. PAVEMENT SURFACE AND JOINT	S		
Sediment has accumulated on pavement			
surface.	□Yes ☑No □N/A		☐Yes ☑No
Trash and debris have accumulated on			
pavement surface or around curbing.	□Yes □No □N/A		☐ Yes ☐ No
Pavement has deteriorated, cracked,	□Yes ☑No □N/A		
settled, or raveled.	Lites PING LIN/A	and the same of th	☐Yes ☑No
Sediment has accumulated in the joints of PICP.	Yes ONO ON/A	MINOR - CAN	☐Yes ☐No
Vegetation is growing in the joints of		FALL ANNUAL	100 ,20110
PICP.	□Yes ☑No □N/A	CLEANING	☐ Yes ☐ No
Gravel is insufficient in the joints of		0 0 ( )2 /0 / / 0 1	
PICP.	☐Yes ☐No ☐N/A		☐Yes ☐No
Additional Notes			
LOT WAS CLEARED / VACUMMED NOVEMBER /2026.			
Next CLEANING PLANNED FOR 2021			
VOLUNTEER & COMMUNITY  EVENT MELA TO MAINTAIN  PAVERS - SEE Photos  Wet weather inspection needed 1981 100			
Wet weather inspection needed Ves No			
wet weather inspection needed \( \subseteq \text{Yes} \)	□ INO		

### East Lot of Permeable Pavers Photo 5-26-2021



East Lot-Showing where gutters outlets on pavers



East lot pavers close-up Photo: 5/26/2021



Permeable paver signage for both lots Photo taken 5-26-2021



On Saturday November 7, 2020 members of St. Gabriel Parish in Concord participated in Community Service Day and spent the day working at St. Casimir Church. St. Gabriel parishioners teamed up with St. Casimir volunteers to provide maintenance of the Northeast Ohio Sewer District Green Infrastructure Project at the church.

Bioretention areas were cleaned out (Earlier this summer mulch was added), permeable pavers were cleaned of moss, sediment, and leaves and vacuumed, and rain barrels were drained for the winter season.

Volunteers also learned of the benefits of the project while providing hands on maintenance of the practices.

To top it off, volunteers picked up trash in the neighborhood and were treated to cabbage and noodles and paczki for lunch!!!





Community Volunteers maintaining Green Infrastructure Project enjoying Polish food after!! November 7, 2020



May 9, 2021 photo of East lot pavers during 1.8' rainfall event



Showing East Lot on May 9, 2021 1.8" rainfall event near outlet of lot where all rain appears to have infiltrated with no offsite runoff observed



# Westlot - Across Street From Permeable Pavement Inspection and Maintenance Checklist Church

Facility: ST (1.5/m11	?		
Location/Address: 8223 Sowinsty CLEVELARP			
Date: 5/24/2/ Time: And Weather Conditions: Date of Last Inspection:			
Inspector: John NIEDZIALPH Title: CPFSCS			
Rain in Last 48 Hours Ves 1 No	If yes, list amount and	timing: Seephotos FX	20m 5/9/
	ig concrete pavement (PI	CP) asphalt concrete other, spec	ify:
Pretreatment: - vegetated filter strip -			□ none
Site Plan or As-Built Plan Available: D			
*Permeable interlocking concrete pavement	(PICP)		
Inspection Item		Comment	Action Needed
1. PRETREATMENT			
Sediment has accumulated.	□Yes □No □N/A		□Yes □No
Trash and debris have accumulated.	□Yes □No □N/A		□Yes □No
2. PAVEMENT TRANSITION AREA			
Non-permeable transition area at			
pavement edges is unstable/deteriorating.	□Yes □No □N/A		☐Yes ☐No
3. DEWATERING			
Standing water is visible on the surface		Some MINOR	
after a rain event.	□Yes □No □N/A		Yes No
4. PAVEMENT SURFACE AND JOINT	S	RAIN EVENT-SEEPH	070
Sediment has accumulated on pavement		•	
surface.	□Yes □No □N/A	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	☐Yes ☑No
Trash and debris have accumulated on			
pavement surface or around curbing.	□Yes □No □N/A		Yes No
Pavement has deteriorated, cracked,	□Yes ☑No □N/A		
settled, or raveled.	LI Yes ZINO LIN/A		☐Yes ☑No
Sediment has accumulated in the joints of PICP.	Yes ONO ON/A	MINOR - CAN WAIT UNTIL	□Yes □No
Vegetation is growing in the joints of PICP.	□Yes ☑No □N/A	FALL ANNUAL CLEANING	□Yes □No
Gravel is insufficient in the joints of			
PICP.	□Yes □No □N/A		Yes No
Additional Notes			
LOT WAS CLEANED / VACUMMED NOVEMBER /2020. NEXT CLEANING PLANNED FOR 2021			
Wet weather inspection needed	□ No		

West lot pavers -photo: May 26, 2021



Close up of West lot pavers in good shape May 26,2021 photo



View of West Lot on May 9, 2021 during 1.8" rain event-minor ponding with good infiltration still visible



## Rain Barrel/Cistern Inspection and Maintenance Checklist

Facility: ST. CASIMIR			
Location/Address: 8223 SOWINSKI CLEVELANT			
Date: 5/26/21 Time: 10 Am Weather Conditions: CLOUD & Date of Last Inspection:			
Inspector: John Wien	7-101Ph Title:	CPFSC	•
Rain in Last 48 Hours	If yes, list amount and timin		
Pretreatment:   downspout screen   g		er/screen 🗆 other, specify:	
Site Plan or As-Built Plan Available:	Yes □ No		
Inspection Item		Comment	Action Needed
1. PRETREATMENT			reedeu
Sediment and debris have accumulated in			
gutter.	□Yes □No □N/A		☐Yes ☐No
The screen or trap is clogged or not			- 6
attached.	□Yes □No □N/A		☐Yes ☐No
2. FOUNDATION			
Barrel foundation is unstable.	□Yes ☑No □N/A		☐Yes ☐No
3. INLETS/DOWNSPOUTS			
Gutters and downspouts joints are	Dayon Della Dayon		
disconnected and/or leaks are present.	□Yes □No □N/A		□Yes □No
Downspouts are disconnected to barrel and/or leaks are present.	□Yes ☑No □N/A		□Yes ZNo
Diverter is disconnected and/or leaks are			7-1
present.	□Yes □No □N/A		☐Yes ☐No
3. SPIGOT			
Visible leaks are present and connections are not tight.	□Yes □N/A		□Yes □No
Valves and knobs do not turn.	□Yes □No □N/A		□Yes □No
4. RAIN BARREL/CISTERN			
Sediment accumulated at bottom of	Day Day-		
barrel.	□Yes □No □N/A		☐ Yes ☐ No
Odor of mildew present or algae is visible inside the barrel.	□Yes □No □N/A		□Yes □No
Cracks or leaks are visible in barrel.	□Yes □No □N/A		☐Yes ☐No
Mosquito larva is visible in barrel.			
	□Yes □No □N/A		☐ Yes ☐ No
5. OVERFLOW STRUCTURE	T T		
Overflow is directed away from the structure or disconnected from the			
downspout.	□Yes □No,□N/A		☐Yes ☐No
Other:	□Yes □No □N/A	<del></del>	□Yes □No
Special Nator: An untrained individual sha		drink water from a sain basel	
Special Notes: An untrained individual should never enter a cistern. Never drink water from a rain barrel or a cistern. Always follow the manufacturer's manual and recommended maintenance schedule.			
Additional Notes			
BARREIS ARE IN 600P			
Shape JUST RECOMNECTED			
AFTER DORMANT THROUGH			
WINTER			
Wet weather inspection needed Ves No			

View of rain barrels 5/26/2021 (Paintings made by students at neighboring Willson Public School)



View of rain barrels connected 5/26/2021



#### Rain Barrell sign May 26, 2021



#### Overall Project sign still in good shape 5/26/2021

