

# CULVERT REPAIR AT BERKSHIRE DRIVE

Macedonia, OH

CUYAHOGA RIVER SOUTH · INDIAN CREEK

## Summary

The invert of a corrugated metal pipe culvert beneath Berkshire Drive in Macedonia was corroded with erosion present at inlet, outlet, and nearby gabions. Culvert was sandblasted to remove rust, re-coated for corrosion resistance, and re-lined with concrete to preserve the integrity of the structure, extending the life of the culvert by another 10-20 years.

## Project Details


**Asset ID(s):** IC00077

**Contract Type:** Quote

**Construction Cost:** \$42,500.00

**Completed Date:** December 18, 2018

**Watershed Team Leader:** Anne Schilling (SchillingA@neorsd.org)



**REGIONAL  
STORMWATER  
MANAGEMENT**