Bioretention Area Inspection and Maintenance Checklist

Facility: West Garden	
Location/Address: East Blvd & MLK	
Date:7/2/2019 Time: 12:47pm Weather Conditions: Sunny Date of Last Inspection: N/A	
Inspector: Crystal Davis, Spencer Nash, Christopher Hartman, Jessica Cotton	Title: Inspection Report
Site Plan or As-Built Plan Available: Yes No	
Inspection Item	Images
DEWATERING	
Standing water is present after 24 hours. If yes, describe	Male Wall
sheen, color, or smell. ☐ Yes ☐ No ✓ NA	
	The state of the s
	115
Action needed.	
□ Yes ☑ No □ NA	
Comments: No additional comments.	A Republic Property of the Pro
INLETS	
INLEIS	
Inlets are in poor structural condition.	
☐ Yes ✓ No ☐ NA	Photo 1.
Sediment has accumulated and/or is blocking the inlets.	
□Yes ☑No □NA	
Enocion is a comming around the inlets	
Erosion is occurring around the inlets. ☐ Yes No ☐ NA	
Action needed. ☐ Yes ✓ No ☐ NA	
Comments: No additional comments.	
VEGETATION	
Vegetation is wilting, discolored, or dying due to disease or	The state of the s
stress.	
☐ Yes ✓ No ☐ NA	
Vegetation needs to be controlled through mowing or	
manual removal.	
✓ Yes □No □ NA Action needed.	Photo 2.
Yes □ No □ NA	
Comments: Applicant needs to conduct routine weeding	
maintenance.	
BIORETENTION MAIN INFILTRATION AREA	
Trash and debris have accumulated. ✓ Yes □ No □ NA	

Sediment has accumulated at the surface. ☐ Yes ✓ No ☐ NA
Topmost layer is caked or crusted over with sediment.
□ Yes ✓ No □ NA
Erosion is evident.
□ Yes 🔽 No □ NA
Mulch is compacted.
1. □ Yes 🔽 No □ NA
Sinkholes or animal borrows are present.
□ Yes ✓ No □ NA
Action needed.
Yes □No □ NA Comments: Trash accumulation near the signage area.
Comments. Trash accumulation hear the signage area.
SIDE SLOPES AND EMBANKMENT
Erosion is evident.
□ Yes 🔽 No □ NA
Sinkholes or animal borrows are present.
☐ Yes ✓ No ☐ NA
Action needed.
☐ Yes ☑ No ☐ NA Comments: No additional comments.
Comments. No additional comments.
OUTLETS AND OVERFLOW STRUCTURE (i.e.,
catch basin)
Outlets or overflow structures in poor structural condition.
☐ Yes ✓ No ☐ NA Sediment, trash or debris is blocking the outlets or
overflow structure.
☐ Yes ✓ No ☐ NA
Erosion is occurring around the outlets or overflow
structure.
□ Yes ✓ No □ NA
Height from surface of practice to top of overflow structure
is insufficient to allow for ponding during rain events.
☐ Yes ✓ No ☐ NA
Action needed.
□Yes ✓ No □ NA
Action needed.
Note: No additional comments.
SUMMARY
Please address the following items:
1. Applicant needs to remove trash that has deposited around signage area (Refer to photo 2).
2. Applicant needs to weed the practice (Refer to photo 1).