

Green Infrastructure Grant Program (GIGP)

Maintenance Inspection Checklist

Site Name: Towpath Trail Stage 3		
Address: Clark Ave and Mary Court		
Inspector's Name:	Date and Time:	
Christopher Hartman, CPESC, CPSWQ, CESSWI	July 16 th 1:57pm	
Overall Notes:		
Ensure sediment-laden runoff from adjacent construction operations is properly managed prior to discharging into the practices. To date a significant amount of sediment has already accumulated within the practices. Practices will need to be restored to original design dimensions once contributing drainage areas are permanently stabilized.		
Ensure there is a watertight seal between the concrete riser sections and the outlet control structures.		
CISTERN (Select yes or no to the following maintenance questions)		
	Debrie notes: Debrie and runoff has deposited in the detention	

CISTERN (Select yes or no to the following maintenance questions)	
Is there debris present?	Debris notes: Debris and runoff has deposited in the detention basins that are near the active construction sites.
Is there a layer of sediment?	Sediment notes: Ponding water at the beginning of the construction site.
Do the inlets provide stable conveyance into facility?	Inlet notes: N/A
Presence of invasive species/weeds?	Invasive notes :N/A
Dead vegetation/exposed soil?	Soil notes: N/A
Evidence of clogging?	Clogging notes: N/A
Evidence of erosion?	Erosion notes'/A
Evidence of standing water?	Standing water notes: N/A



Green Infrastructure Grant Program (GIGP)

Maintenance Inspection Checklist

CISTERN (Select yes or no to the following maintenance questions)	
Filter media too low?	Filter media low notes'/A
Evidence of blockage in or around outlet?	Blockage notes'/A
Replant?	Replant notes
Complaints from local residents?	Complaints notes

Follow Up Comments

8/13

After the site visit, the applicant said they would clean up the practices after construction. Plan to follow up on October 15th, 2018. They will not be conducting any plantings.

Site Visit 10/18/18- The sediment that has deposited in the Stormwater Wetlands has accumulated at the bottom. Construction is still not finished.



Green Infrastructure Grant Program (GIGP)

Maintenance Inspection Checklist

PHOTO(S) INFORMATION

