
## Bioretention Area Inspection and Maintenance Checklist

Facility: ADMIN PARKING LOT	- clerkland MET	Monks	
Location/Address: 410)	PACKWAY	cleveland of 49144	
		Date of Last Inspection	
Inspector: J. Pods-Fam		tle: DIRECTOR OF CONSTRUCT	
Rain in Last 48 Hours Yes No	If yes, list amount and	timing: 0.10 M within 2403	950
Pretreatment: Avegetated filter strip  Site Plan or As-Built Plan Available:	swale Duri grass 10	rebay   other, specify:	none –
Site Fian of As-Built Fian Available:	res UNO		
	The state of the s		Action
Inspection Item		Comment	Needed
1. PRETREATMENT			
Sediment has accumulated.	□Yes ☑No □N/A		□Yes □No
Trash and debris have accumulated.	□Yes ☑No □N/A		Yes No
2. DEWATERING			
Standing water is present after 24 hours. If yes, describe sheen, color, or smell.	□Yes ☑No □N/A		☐Yes ☐No
3. INLETS			
Inlets are in poor structural condition.	□Yes ☑No □N/A		□Yes □No
Sediment has accumulated and/or is blocking the inlets.	□Yes ☑No □N/A		□Yes □No
Erosion is occurring around the inlets.	□Yes □No □N/A		☐Yes ☐No
3. VEGETATION			
Vegetation is wilting, discolored, or dying due to disease or stress.	□Yes ☑No □N/A		□Yes □No
Vegetation needs to be controlled through	□Yes ☑No □N/A		□Yes □No
mowing or manual removal.			☐ Yes ☐ No
4. BIORETENTION MAIN INFILTRA	HON AREA		1
Trash and debris have accumulated.	□Yes □No □N/A		□Yes □No
Sediment has accumulated at the surface.	□Yes □No □N/A	Nothing Usible	□Yes □No
Topmost layer is caked or crusted over with sediment.	□Yes ☑No □N/A		□Yes □No
Erosion is evident.	□Yes □No □N/A	WILL CONTINUE TO MONITE	□Yes □No
Mulch is compacted.	□Yes □No □N/A		□Yes □No
Sinkholes or animal borrows are present.	₩Yes □No □N/A	ALOTEDREP BUNNY BIPME	□Yes □No
5. SIDE SLOPES AND EMBANKMENT	Γ	, ,	
Erosion is evident.	✓Yes □No □N/A	MWIR, WILL MUNITER	□Yes □No
Sinkholes or instability is evident.	□Yes ☑No □N/A		□Yes □No
6. OUTLETS AND OVERFLOW STRU	CTURE (i.e., catch basin)		
Outlets or overflow structures in poor structural condition.	□Yes ☑No □N/A		□Yes □No
Sediment, trash or debris is blocking the outlets or overflow structure.	□Yes □No □N/A		□Yes □No
Erosion is occurring around the outlets or overflow structure.	□Yes ☑No □N/A		□Yes □No
Height from surface of practice to top of overflow structure is insufficient to allow	□Yes ☑No □N/A		□Yes □No

for ponding during rain events.

Additional Notes		
.25		
Wet weather inspection needed	Yes DXo	T-932 - 42



## Permeable Pavement Inspection and Maintenance Checklist

		emelike	
Location/Address: 410) FWW		Cleveland of 4414	
	eather Conditions: Ch	Date of Last Inspection	
Inspector: T. Polynom	If you list amount and	tle: Dream of CHISARYOTIM	
Rain in Last 48 Hours Types   No	If yes, list amount and	CP) sphalt concrete other, spec	ajo
Pretreatment: vegetated filter strip	swale turf grass for	rebay other, specify: NAML	ny: □ none
Site Plan or As-Built Plan Available:	res 🗆 No		- 110110
*Permeable interlocking concrete pavemen	t (PICP)		
Inspection Item		Comment	Action Needed
1. PRETREATMENT			
Sediment has accumulated.	□Yes □No □N/A		□Yes □No
Trash and debris have accumulated.	□Yes □No ☑N/A		Yes No
2. PAVEMENT TRANSITION AREA	Т		_
Non-permeable transition area at pavement edges is unstable/deteriorating.  3. DEWATERING	□Yes ☑No □N/A	mire serving will minker	□Yes □√0
Standing water is visible on the surface			T
after a rain event.	Yes No N/A		☐Yes ☐No
4. PAVEMENT SURFACE AND JOIN	rs		
Sediment has accumulated on pavement surface.	□Yes □No □N/A		□Yes □No
Trash and debris have accumulated on pavement surface or around curbing.	□Yes □No □N/A		☐Yes ☐No
Pavement has deteriorated, cracked, settled, or raveled.	□Yes □No □N/A		□Yes □No
Sediment has accumulated in the joints of	✓ Yes □No □N/A	Anus Isms ned deaned you	
PICP.  Vegetation is growing in the joints of			
PICP. Gravel is insufficient in the joints of	□Ves □No □N/A	Soirs deed Virginial RE-Filled	□Yes □No
PICP.	☐Yes ☐No ☐N/A		☐Yes ☐No
Additional Notes			
Paver IDINTS Need Vacumed Cleaned power washed ADV RE-FILLED. REAMEDBURY ROTE OF PAVIS IS STILL OK & WILL BE EVW BETTER AFTER Cleaning and REFILLING JOINTS.			
Wet weather inspection needed □ Yes	□ No		

## **Underground Detention System Inspection and Maintenance Checklist**

Facility: ADMIN PACION LOT - clayeland	MUTROPICKS			
Location/Address: 4101 FUTEN PARKING	claveline.	0)) 44) 44		
Date: 6 14 21 Time: 12: 40 Weather Conditions:		Date of Last Inspection:		
Inspector: T. Austream	Title: Dice To	e of consportation		
Rain in Last 48 Hours Wes I No If yes, list amount and timing: 0,10 10 W120W Z hr				
Pretreatment: vegetated filter strip swale turf grass forebay other, specify:				
Site Plan or As-Built Plan Available: Des 🗆 No				

Inspection Item		Comment	Action Needed
1. PRETREATMENT			
Sediment has accumulated.	□Yes □No □N/A		□Yes □No
Trash and debris have accumulated.	□Yes □No □N/A		□Yes □No
2. INLETS			
Inlets are in poor structural condition.	□Yes ☑No □N/A		□Yes □No
Sediment, trash, or debris have accumulated and/or is blocking the inlets.  3. CHAMBERS	□Yes ☑No □N/A		□Yes □No
Sediment accumulation threshold has been reached.	□Yes ☑No □N/A	<del></del> .	☐Yes ☐No
Trash and debris have accumulated in chambers.	□Yes 望No □N/A		□Yes □No
4. OTHER SYSTEM COMPONENTS			
Structural deterioration is evident.	□Yes □N₀ □N/A		□Yes □No
5. OUTLETS			
Outlets in poor structural condition.	□Yes □N₀ □N/A		□Yes □No
Sediment, trash or debris are blocking outlets.	□Yes ☑No □N/A		□Yes □No
Erosion is occurring around outlets.	□Yes □No □N/A		□Yes □No
6. OTHER			
Evidence of ponding water on area draining to system.	□Yes □No □N/A		□Yes □No
Evidence that water is not being conveyed through the system.	□Yes ☑No □N/A		□Yes □No
Additional Notes			
Wet weather inspection needed Ves	¬ No		

<sup>\*</sup>Do not enter underground detention chambers to inspect system unless Occupational Safety & Health Administration (OSHA) regulations for confined space entry are followed.

<sup>\*</sup>Follow inspection and maintenance instructions and schedules provided by system manufacturer and installer.

<sup>\*</sup> Properly dispose of all wastes.