## **Permeable Pavement Inspection and Maintenance Checklist**

Facility: McGregor Senior Assisted Living			
Location/Address: 14850 Private Drive			
Date: 04/29/2021 Time: 9:00AM Weather Conditions: Raining Date of Last Inspection: 07/15/2020			
Inspector:       Eric Mondok       Title:       Facilities Director         Rain in Last 48 Hours       Yes □ No       If yes, list amount and timing:			
Rain in Last 48 Hours Yes   No   If yes, list amount and timing:  Pavement Type: permeable interlocking concrete pavement (PICP)   asphalt   concrete   other, specify:			
Pretreatment: vegetated filter strip swale turf grass forebay other, specify: none Site Plan or As-Built Plan Available: Yes No			
*Permeable interlocking concrete pavement (PICP)			
Inspection Item		Comment	Action Needed
1. PRETREATMENT			1
Sediment has accumulated.	□Yes □No N/A		□Yes □No
Trash and debris have accumulated.	□Yes □No ☑N/A		□Yes □No
2. PAVEMENT TRANSITION AREA			1
Non-permeable transition area at pavement edges is unstable/deteriorating.	□Yes ☑No □N/A		□Yes □No
3. DEWATERING			
Standing water is visible on the surface after a rain event.	□Yes ☑No □N/A		□Yes □No
4. PAVEMENT SURFACE AND JOINT	<u>S</u>		
Sediment has accumulated on pavement surface.	□Yes ∇No □N/A		□Yes □No
Trash and debris have accumulated on pavement surface or around curbing.	□Yes ☑No □N/A		□Yes □No
Pavement has deteriorated, cracked, settled, or raveled.	□Yes ▼No □N/A		□Yes □No
Sediment has accumulated in the joints of PICP.	√Yes □No □N/A		<b>✓</b> Yes □No
Vegetation is growing in the joints of PICP.	□Yes ☑No □N/A		□Yes □No
Gravel is insufficient in the joints of PICP.	Yes DNo DN/A		▼Yes □No
Additional Notes	-		1
Some areas need vacuumed and sediment added.			
Wet weather inspection needed □ Yes ▼No			