

# CHIPPEWA CREEK STABILIZATION AT CONDOMINIUMS IN BRECKSVILLE

## Brecksville, OH

CUYAHOGA RIVER SOUTH · CHIPPEWA CREEK

### Summary

Chippewa Creek was eroding its right streambank in this area. The eroding stream bank is within 12 feet of the Chippewa Creek Condominiums and approximately 6 feet from a parallel local sanitary sewer. The erosion has also exposed storm sewer pipe and headwalls. The project stabilized the eroding stream bank and protected these sewer infrastructure assets.

### Project Details


**Asset ID(s):** CC00032

**Contract Type:** Design/Bid/Build

**Construction Cost:** \$1,092,019.63

**Completed Date:** May 19, 2021

**Watershed Team Leader:** Anne Schilling (SchillingA@neorsd.org)



**REGIONAL  
STORMWATER  
MANAGEMENT**