

BALDWIN CREEK BANK STABILIZATION AT PLEASANT VALLEY ROAD

Parma, OH

ROCKY RIVER · BALDWIN CREEK

Summary

This project repaired an eroding streambank on Baldwin Creek along West Pleasant Valley Road in Parma. The channel's incised right bank was a near vertical drop, approximately 4 feet high and 85 feet long. The restoration project included the use of live branch layering and rock toe protection restoration practices implemented in locations where unstable streambanks were likely to contribute to further sediment loading and reduced flood storage capacity within the affected waterway.

Project Details


Asset ID(s): BD00250

Contract Type: Quote

Construction Cost: \$23,220.00

Completed Date: April 8, 2018

Watershed Team Leader: Nicole Velez (velezn@neorsd.org)



**REGIONAL
STORMWATER
MANAGEMENT**