

STREAMBANK STABILIZATION AT JOSEPHINE DR. IN INDEPENDENCE

Independence, OH

CUYAHOGA RIVER NORTH · HEMLOCK CREEK

Summary

Failing gabion baskets and left bank erosion were stabilized by grading the bank to a gentle slope and planting native vegetation and live stakes. A rock vane was placed along the stream invert to maintain grade.

Project Details


Asset ID(s): HC00026

Contract Type: Design/Bid/Build

Construction Cost: \$60,891.00

Completed Date: August 31, 2021

Watershed Team Leader: Anne Schilling (SchillingA@neorsd.org)



**REGIONAL
STORMWATER
MANAGEMENT**