

BRANDYWINE CREEK BANK STABILIZATION NORTH OF BRANDYWINE DRIVE

Hudson, OH

CUYAHOGA RIVER SOUTH · BRANDYWINE CREEK

Summary

This project stabilized the left bank of Brandywine Creek where it was eroding behind several residences along Brandywine Dr. in Hudson. Over 175ft of streambank was actively eroding, undercut, and slumping into the stream, leading to property loss. Rock protection was installed along the left bank in the form of a stacked boulder wall. Native vegetation was then planted along the right bank to ensure stability on both sides of the stream.

Project Details

Asset ID(s): BR00234

Contract Type: Quote

Construction Cost: \$47,775.00

Completed Date: November 3, 2020

Watershed Team Leader: Anne Schilling (SchillingA@neorsd.org)

